

## Sand Hills-Federal 1-19

Inspection# 673402623

Ruts transporting sediment  
onto location.

11/4/2015

Inspection 673402623



Ruts transporting sediment  
onto location.

7/23/2015

Inspection 673402266



Sediment being  
transported onto location.

11/4/2015

Inspection 673402623



Sediment being transported  
onto location.

11/4/2015

Inspection 673402623

