

Sand Hills Fed 43-20

Inspection# 673402626

Ruts in access road
transporting sediment.



Ruts in access road
transporting sediment.

