



Photo 1. View of equipment in southwestern portion of the project area.



Photo 2. View of eastern portion of the project area from the southeastern corner facing northward. Revegetation species such as intermediate wheatgrass (*Thinopyron intermedium*), western wheatgrass (*Pascopyron smithii*), and dropseed (*Sporobolus* sp.) are established here.



Photo 3. View of project area from southeastern corner facing center. Unused fencing and piping needs to be removed.



Photo 3. View of northern portion of the project area from northeastern corner facing westward.



Photo 4. View of open water adjacent to northern portion of the project area. Vegetation on slope appears to be sufficiently stabilizing the slope at this time.