



photo 1: Facing west towards the reclaimed access road.



photo 2: Facing west along the reclaimed access road.



photo 3: Vegetation growth emerging along the access road.



photo 4: Facing northwest along the reclaimed access road.



photo 5: Facing northwest along the reclaimed access road.



photo 6: Facing northwest along the reclaimed access road.



photo 7: Facing north along the reclaimed access road.



photo 8: Facing east towards the location.



photo 9: Facing southeast towards the location.



photo 10: Well sign at the location.



photo 11: South side of the location facing northwest.



photo 12: South side of the location facing south.