



photo 1: South side of the location facing west..



photo 2: East side of the location facing south at area of the location that looks to have been seeded and mulched.



photo 3: East side of the location facing south at area of the location that looks to have been seeded and mulched.




photo 4: Southwest side of the location facing north towards the pit.