

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:
11/13/2015Document Number:
666801616Overall Inspection:
SATISFACTORY**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | 270055 | 334637 | Murray, Richard | <input type="checkbox"/> | |

Operator Information:OGCC Operator Number: 11050Name of Operator: BROWN INC* TOMAddress: 555 17TH ST STE 1850City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|------------------------------|---------|
| Murray, Richard | 970-623-9782 | G.Richard.Murray@state.co.us | |

Compliance Summary:QtrQtr: NWNE Sec: 1 Twp: 7S Range: 94W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Action Required | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|-------------------------------|----------|----------------|-----------------|
| 11/30/2006 | 200101315 | SR | AL | SATISFACTORY | P | Pass | No |

Inspector Comment:Inspection is for well with the status of Abandoned Location**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 211405 | WELL | PR | 10/01/1999 | GW | 045-07165 | SAVAGE 1-13 | PR |
| 270054 | WELL | PR | 10/27/2005 | GW | 045-09443 | SAVAGE 1-6B (RBI) | PR |
| 270055 | WELL | AL | 08/11/2004 | LO | 045-09445 | SAVAGE 1-231 | AL |
| 270056 | WELL | PR | 12/14/2004 | GW | 045-09444 | SAVAGE 1-7A (RB1) | PR |

Equipment:Location Inventory

| | | | |
|-----------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Motors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Emergency Contact Number (S/A/V): _____

Inspector Name: Murray, Richard

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?

Venting:

| Yes/No | Comment |
|--------|---------|
| | |
| | |

Flaring:

| Type | Satisfactory/Action Required | Comment | Corrective Action | CA Date |
|------|------------------------------|---------|-------------------|---------|
| | | | | |

Predrill

Location ID: 270055

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 270055 Type: WELL API Number: 045-09445 Status: AL Insp. Status: AL

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Inspector Name: Murray, Richard

| | | | | |
|---|-------------|-------|-----|------|
| DWR Receipt Num: | Owner Name: | GPS : | Lat | Long |
| Field Parameters: | | | | |
| Sample Location: _____ | | | | |
| Emission Control Burner (ECB): _____ | | | | |
| Comment: _____ | | | | |
| Pilot: _____ Wildlife Protection Devices (fired vessels): _____ | | | | |

Reclamation - Storm Water - Pit

Interim Reclamation:

| | |
|---|---|
| Date Interim Reclamation Started: _____ | Date Interim Reclamation Completed: _____ |
| Land Use: _____ | |
| Comment: _____ | |

| | | | | |
|--------|---|----------|----------|---------------|
| 1003a. | Debris removed? _____ | CM _____ | CA _____ | CA Date _____ |
| | Waste Material Onsite? _____ | CM _____ | CA _____ | CA Date _____ |
| | Unused or unneeded equipment onsite? _____ | CM _____ | CA _____ | CA Date _____ |
| | Pit, cellars, rat holes and other bores closed? _____ | CM _____ | CA _____ | CA Date _____ |
| | Guy line anchors removed? _____ | CM _____ | CA _____ | CA Date _____ |
| | Guy line anchors marked? _____ | CM _____ | CA _____ | CA Date _____ |

| | |
|--|--|
| 1003b. Area no longer in use? _____ | Production areas stabilized ? _____ |
| 1003c. Compacted areas have been cross ripped? _____ | |
| 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____ | |
| Cuttings management: _____ | |
| 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____ | |
| Production areas have been stabilized? _____ | Segregated soils have been replaced? _____ |

RESTORATION AND REVEGETATION

Cropland

| | | |
|-------------------------|-------------------|---------------------------------------|
| Top soil replaced _____ | Recontoured _____ | Perennial forage re-established _____ |
|-------------------------|-------------------|---------------------------------------|

Non-Cropland

| | | |
|-------------------------|-------------------|------------------------|
| Top soil replaced _____ | Recontoured _____ | 80% Revegetation _____ |
|-------------------------|-------------------|------------------------|

| | | | |
|-----------------------------------|----------------------------|----------|---------------|
| 1003 f. | Weeds Noxious weeds? _____ | CA _____ | CA Date _____ |
| Comment: _____ | | | |
| Overall Interim Reclamation _____ | | | |

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: No visual sign of well

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Pass _____ Well Release on Active Location ☐ Multi-Well Location ☒

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT