



Photo#1: Overview of Location, view to SE.



Photo #2: Location has not been recontoured.



Photo #3 Water pooling on inside of berm area, evidence of vehicle traffic, Cut Slope in background.



Photo #4: Campfire leavings.