

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
11/18/2015

Document Number:
666801626

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>270355</u>	<u>335076</u>	<u>Murray, Richard</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>96850</u>
Name of Operator:	<u>WPX ENERGY ROCKY MOUNTAIN LLC</u>
Address:	<u>PO BOX 370</u>
City:	<u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@wpxenergy.com	Field Inspections

Compliance Summary:

QtrQtr:	<u>SENW</u>	Sec:	<u>29</u>	Twp:	<u>6S</u>	Range:	<u>94W</u>
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
05/03/2011	200310111	PR	PR	SATISFACTORY			No
03/01/2011	200302433	PR	PR	SATISFACTORY			No
06/08/2009	200213592	PR	PR	SATISFACTORY			No
12/26/2006	200104993	PR	PR	SATISFACTORY	I	Pass	No

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
270355	WELL	PR	05/11/2004	GW	045-09533	CLOUGH RWF 322-29	PR	<input checked="" type="checkbox"/>
270359	WELL	PR	05/11/2004	GW	045-09532	CLOUGH RWF 22-29	PR	<input checked="" type="checkbox"/>
280050	WELL	PR	04/02/2006	GW	045-11162	CLOUGH RWF 522-29	PR	<input checked="" type="checkbox"/>
280051	WELL	PR	03/27/2006	GW	045-11163	CLOUGH RWF 21-29	PR	<input checked="" type="checkbox"/>
280052	WELL	PR	02/13/2006	GW	045-11164	CLOUGH RWF 422-29	PR	<input checked="" type="checkbox"/>
280053	WELL	PR	04/02/2006	GW	045-11165	CLOUGH RWF 423-29	PR	<input checked="" type="checkbox"/>
280054	WELL	PR	03/27/2006	GW	045-11166	CLOUGH RWF 23-29	PR	<input checked="" type="checkbox"/>
288284	WELL	PR	12/08/2006	GW	045-13183	CLOUGH RWF 512-29	PR	<input checked="" type="checkbox"/>

288285	WELL	PR	12/08/2006	GW	045-13182	CLOUGH RWF 412-29	PR	<input checked="" type="checkbox"/>
288286	WELL	PR	12/08/2006	GW	045-13181	CLOUGH RWF 312-29	PR	<input checked="" type="checkbox"/>

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
BATTERY	SATISFACTORY	AIRS ID 045-1203-001		
CONTAINERS	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Equipment:					
Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Horizontal Heated Separator	10	SATISFACTORY			
Ancillary equipment	3	SATISFACTORY			
Plunger Lift	10	SATISFACTORY			

Venting:	
Yes/No	Comment
YES	Bradenhead valves open

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 270355

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 270355 Type: WELL API Number: 045-09533 Status: PR Insp. Status: PR

Producing Well

Comment: **Plunger lift**

Facility ID: 270359 Type: WELL API Number: 045-09532 Status: PR Insp. Status: PR

Producing Well

Comment: **Plunger lift**

Facility ID: 280050 Type: WELL API Number: 045-11162 Status: PR Insp. Status: PR

Producing Well

Comment: **Plunger lift**

Facility ID: 280051 Type: WELL API Number: 045-11163 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Facility ID: 280052 Type: WELL API Number: 045-11164 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Facility ID: 280053 Type: WELL API Number: 045-11165 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Facility ID: 280054 Type: WELL API Number: 045-11166 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Facility ID: 288284 Type: WELL API Number: 045-13183 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Facility ID: 288285 Type: WELL API Number: 045-13182 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Facility ID: 288286 Type: WELL API Number: 045-13181 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS: _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): N

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? Pass CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Inspector Name: Murray, Richard

Access Roads Regraded _____ Contoured _____ Culverts removed _____
 Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Slope Roughening	Pass					
		Gravel	Pass			
Ditches	Pass					
Seeding	Pass					

S/A/V: SATISFACTOR Corrective Date: _____
 Y _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666801626	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3724359