



photo 1: Well sign.



photo 2: Facing west towards the location.



**photo 3:** East side of the location facing south.



**photo 4:** Facing west towards the production equipment.



photo 5: Oily fluid appeared to be sprayed on the ground.



photo 6: Point where fluid may have been released from.