



photo 1: Northeast corner of the location facing south.



photo 2: Northeast corner of the location facing west,



photo 3: Water leak is dripping out of the well head.



photo 4: South side of the location facing north.