

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
11/19/2015

Document Number:
679900726

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>207403</u>	<u>321593</u>	<u>Welsh, Brian</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>70430</u>
Name of Operator:	<u>PINTAIL PETROLEUM LTD</u>
Address:	<u>225 N. MARKET #300</u>
City:	<u>WICHITA</u> State: <u>KS</u> Zip: <u>67202</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
	316-263-2243	pintail@pintailpetroleum.com	

Compliance Summary:

QtrQtr: NESE Sec: 7 Twp: 14S Range: 44W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
08/04/2014	668602984	PR	PR	ACTION REQUIRED	P		No
01/17/2013	668600245	PR	PR	SATISFACTORY			No
12/01/2011	663900186	PR	PR	SATISFACTORY	P		No
05/25/2011	200311164	PR	PR	SATISFACTORY			No
08/17/2010	200266991	PR	PR	SATISFACTORY			No
07/01/2010	200258828	PR	PR	ACTION REQUIRED			Yes
01/05/2010	200226173	PR	PR	ACTION REQUIRED			Yes
05/14/2009	200210328	PR	PR	ACTION REQUIRED			Yes
02/04/2008	200126427	PR	PR	SATISFACTORY			No
11/06/2006	200098622	PR	PR	SATISFACTORY		Pass	No
04/03/2002	200025653	PR	PR	ACTION REQUIRED		Fail	Yes
05/19/1999	500138583	PR	PR			Pass	No
11/07/1997	500138582	PR	PR			Pass	No
06/13/1996	500138581	PR	PR			Pass	Yes
08/14/1995	500138580	PR	PR			Pass	No
06/27/1995	500138579	PR	PR			Fail	Yes
12/10/1993	500138578		PR			Pass	No

Inspector Comment:

Related Facilities:

Inspector Name: Welsh, Brian

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
114922	PIT		09/23/1999		-	CHAMPLIN-COBB 1	<input type="checkbox"/>
207403	WELL	PR	04/18/1982	OW	017-06338	CHAMPLIN-COBB 1	PR <input checked="" type="checkbox"/>

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY	DIRT ROAD THROUGH FARM GROUND		

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
BATTERY	SATISFACTORY	LEASE SIGN MOUNTED TO STAIRS AT TANK BATTERY		
WELLHEAD	SATISFACTORY	LEASE SIGN BY UNIT		
TANK LABELS/PLACARDS	SATISFACTORY	STICKERS ON TANKS		

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

Multiple Spills and Releases?

Equipment:

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
FWKO	1	SATISFACTORY	8BBL		
Prime Mover	1	SATISFACTORY	ELECTRIC MOTOR		
Pump Jack	1	SATISFACTORY	AMERICAN UNIT MODEL 456		
Ancillary equipment	2	SATISFACTORY	ELECTRIC PANEL AND CATHODIC RECTIFIER		

Facilities: New Tank Tank ID: _____

Inspector Name: Welsh, Brian

Contents	#	Capacity	Type	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST	38.847530,-102.369900

S/A/V:	SATISFACTORY	Comment:	
--------	--------------	----------	--

Corrective Action:		Corrective Date:	
--------------------	--	------------------	--

Paint

Condition	
Other (Content)	_____
Other (Capacity)	_____
Other (Type)	_____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment				

Venting:

Yes/No	Comment
YES	1" CASING VENT

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 207403

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: SATISFACTORY **Comment:** NO COA'S

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 207403 Type: WELL API Number: 017-06338 Status: PR Insp. Status: PR

Producing Well

Comment: PRODUCING

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Inspector Name: Welsh, Brian

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

S/A/V: SATISFACTOR Corrective Date: _____

Y _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT