

Plat 1A

**LOCATION
PHOTOS
E-W**



PHOTO FACING EAST, TAKEN ON OCTOBER 14, 2015



PHOTO FACING WEST TAKEN ON OCTOBER 14, 2015

Battlement Mesa 26-K-795
NWSW, SECTION 26, T. 7 S., R. 95 W.

Caerus Piceance LLC



LOCATION PHOTOS

CONSTRUCTION SURVEYS, INC.
0012 SUNRISE BLVD. SILT, CO
81652 (970)876-5753

SURVEY BY: REW 10/13/15

PDOP: 1.8

DRAWN BY: REW 11/07/15

DWG: CAERUS\BM26K-795

REVISED:

Plat 1A

**LOCATION
PHOTOS
N-S**



PHOTO FACING NORTH, TAKEN ON OCTOBER 14, 2015



PHOTO FACING SOUTH, TAKEN ON OCTOBER 14, 2015

Battlement Mesa 26-K-795
NWSW, SECTION 26, T. 7 S., R. 95 W.

Caerus Piceance LLC



LOCATION PHOTOS

CONSTRUCTION SURVEYS, INC.
0012 SUNRISE BLVD. SILT, CO
81652 (970)876-5753

SURVEY BY: REW 10/13/15

PDOP: 1.9

DRAFTED BY: REW 11/06/15

DWG: BM26K-795

REVISED: