

## Klaenhammer 2

Inspection# 673402667

No wellhead sign.



Former operator on tank label. Label beginning to peel.

