



Photo 1. View of rutting on well pad surface approximately 10 inches deep. Pen in foreground can be used for scale.



Photo 2. View of muddy tire tracks at eastern exit that appear to be carrying mud off of the location onto graveled road surface.





Photo 3. View of muddy tire tracks at western exit that appear to be carrying mud off of the location onto graveled road surface (in foreground).



Photo 4. View of project area from southeastern corner facing center.





Photo 5. View of northern portion of project area from northeastern corner facing westward. Big sagebrush (*Artemisia tridentata*), rubber rabbitbrush (*Chrysothamnus nauseosus*), purple three-awn (*Aristida purpurea*), and cheatgrass (*Bromus tectorum*) are common here.