

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

11/23/2015

Document Number:

674702089

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	335642	335642	LONGWORTH, MIKE	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, General	970-285-2665	cogcc.inspections@encana.com	EnCana Inspection email

Compliance Summary:QtrQtr: SENE Sec: 26 Twp: 5S Range: 96W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
07/28/2015	674701652			SATISFACTORY			No
02/13/2015	674701014			ACTION REQUIRED			No
07/30/2014	674700140			SATISFACTORY			No
12/20/2013	663902539			SATISFACTORY			No
05/30/2012	663800367			SATISFACTORY			No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
280184	WELL	PR	12/01/2010	GW	045-11214	N PARACHUTE WF09B-26H26A596	PR	<input checked="" type="checkbox"/>
280469	WELL	PR	04/10/2006	GW	045-11261	N PARACHUTE WF08D-26H26A596	PR	<input checked="" type="checkbox"/>
296238	WELL	AL	06/26/2012	LO	045-15954	ENCANA RPW 333-26-596	AL	<input type="checkbox"/>
296240	WELL	AL	06/26/2012	LO	045-15955	ENCANA RPW 334-26-596	AL	<input type="checkbox"/>
296241	WELL	AL	06/26/2012	LO	045-15956	ENCANA RPW 432-26-596	AL	<input type="checkbox"/>
296242	WELL	AL	06/26/2012	LO	045-15957	ENCANA RPW 443-26-596	AL	<input type="checkbox"/>
296243	WELL	AL	06/26/2012	LO	045-15958	ENCANA RPW 42-26-596	AL	<input type="checkbox"/>

Inspector Name: LONGWORTH, MIKE

296244	WELL	AL	06/26/2012	LO	045-15959	ENCANA RPW 533-26-596	AL	
296245	WELL	AL	06/26/2012	LO	045-15960	ENCANA RPW 34-26-596	AL	
296246	WELL	AL	06/26/2012	LO	045-15961	ENCANA RPW 434-26-596	AL	
296247	WELL	AL	06/26/2012	LO	045-15962	ENCANA RPW 534-26-596	AL	
296248	WELL	AL	06/26/2012	LO	045-15963	ENCANA RPW 543-26-596	AL	
296249	WELL	AL	06/26/2012	LO	045-15964	ENCANA RPW 43-26-596	AL	
296250	WELL	AL	06/26/2012	LO	045-15965	ENCANA RPW 433-26-596	AL	
296251	WELL	AL	06/26/2012	LO	045-15966	ENCANA RPW 32-26-596	AL	
296252	WELL	AL	06/26/2012	LO	045-15967	ENCANA RPW 342-26-596	AL	
296253	WELL	AL	06/26/2012	LO	045-15968	ENCANA RPW 332-26-596	AL	
296254	WELL	AL	06/26/2012	LO	045-15969	ENCANA RPW 33-26-596	AL	
296255	WELL	AL	06/26/2012	LO	045-15970	ENCANA RPW 341-26-596	AL	
296352	WELL	AL	06/26/2012	LO	045-15996	ENCANA RPW 442-26-596	AL	

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Signs/Marker:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
BATTERY	SATISFACTORY			
WELLHEAD	SATISFACTORY			
TANK LABELS/PLACARDS	SATISFACTORY			
CONTAINERS	SATISFACTORY			

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: _____

Comment: **800-791-7691**

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

Inspector Name: LONGWORTH, MIKE

☐ Multiple Spills and Releases?**Equipment:**

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Horizontal Heated Separator	2	SATISFACTORY			
Bird Protectors	2	SATISFACTORY			
Plunger Lift	2	SATISFACTORY			

Facilities:☐ New Tank

Tank ID: _____

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST	,

S/A/V: SATISFACTORY

Comment:

Corrective Action:

Corrective Date:

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) 120 bbls

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				

Corrective Action

Corrective Date

Comment

Facilities:☐ New Tank

Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST	,

S/A/V: SATISFACTORY

Comment:

Corrective Action:

Corrective Date:

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				

Corrective Action

Corrective Date

Comment

Facilities:☐ New Tank

Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CONDENSATE	1	OTHER	STEEL AST	,

Inspector Name: LONGWORTH, MIKE

S/A/V:	SATISFACTORY	Comment:				
Corrective Action:					Corrective Date:	
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)	250 bbls					
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Corrective Action					Corrective Date	
Comment						
Facilities: <input type="checkbox"/> New Tank Tank ID: _____						
Contents	#	Capacity	Type	SE GPS		
PRODUCED WATER	1	<100 BBLS	STEEL AST	,		
S/A/V:	SATISFACTORY	Comment:				
Corrective Action:					Corrective Date:	
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)	80 bbls					
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal						
Corrective Action					Corrective Date	
Comment						
<u>Venting:</u>						
Yes/No	Comment					
NO						
<u>Flaring:</u>						
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date		

Predrill

Location ID: 335642

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 280184 Type: WELL API Number: 045-11214 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Facility ID: 280469 Type: WELL API Number: 045-11261 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Environmental**Spills/Releases:**

Inspector Name: LONGWORTH, MIKE

Type of Spill: _____	Description: _____	Estimated Spill Volume: _____
Comment: _____		
Corrective Action: _____		Date: _____
Reportable: _____	GPS: Lat _____	Long _____
Proximity to Surface Water: _____		Depth to Ground Water: _____

Water Well:		Lat _____	Long _____
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	_____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a.	Debris removed?	Pass	CM	_____	CA Date _____
	CA	_____			_____
	Waste Material Onsite?	Pass	CM	_____	CA Date _____
	CA	_____			_____
	Unused or unneeded equipment onsite?	Pass	CM	_____	CA Date _____
	CA	_____			_____
	Pit, cellars, rat holes and other bores closed?	_____ CM _____			CA Date _____
	CA	_____			_____
	Guy line anchors removed?	_____ CM _____			CA Date _____
	CA	_____			_____
	Guy line anchors marked?	_____ CM _____			CA Date _____
	CA	_____			_____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Inspector Name: LONGWORTH, MIKE

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐

Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Gravel	Pass					
Berms	Pass					
		Compaction	Pass			
Check Dams	Pass					
Ditches	Pass					
				MHSP	Pass	
		Ditches	Pass			
		Culverts	Pass			
Seeding	Pass					
		Check Dams	Pass			

S/A/V: SATISFACTOR _____

Corrective Date: _____

Y

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT