

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:  
11/11/2015Document Number:  
679900699

Overall Inspection:

**ACTION REQUIRED****FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	205369	320931	Welsh, Brian	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 18600Name of Operator: COLORADO INTERSTATE GAS COMPANY LLCAddress: P O BOX 1087City: COLORADO State: CO Zip: 80944

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☒ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
Lively, Kevin	970-867-4243	kevin_lively@kindermorgan.com	

**Compliance Summary:**QtrQtr: NWNW Sec: 17 Twp: 34S Range: 42W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
11/18/2014	668500568	PR	PR	SATISFACTORY	I		No
07/26/2011	200316631	PR	AO	SATISFACTORY			No
11/05/2009	200222066	PM	AO	SATISFACTORY			No
11/13/2007	200121795	ES	PR	SATISFACTORY			No
10/12/2007	200120799	PR	PR	SATISFACTORY			No
01/12/2001	200013469	PR	AC	SATISFACTORY	I	Pass	No
02/29/2000	200003995	PR	AC	SATISFACTORY	I	Pass	No
04/16/1999	500135143	PR	PR			Pass	No
05/28/1998	500135142	PR	PR			Pass	No
02/18/1997	500135140	PR	PR			Pass	No
06/30/1995	500135139	PR	AC			Pass	No

**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
205369	WELL	PR	02/01/2015	OW	009-05050	Flank 16	PA	<input checked="" type="checkbox"/>

**Equipment:**Location Inventory

Inspector Name: Welsh, Brian

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

### Location

#### Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date
Access	SATISFACTORY	DIRT ROADTHROUGH PASTURE		

#### Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
WELLHEAD	SATISFACTORY	LEASE SIGN BY FENCE AT METERRUN		

Emergency Contact Number (S/A/V): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

#### Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

#### Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
OTHER	SATISFACTORY	METAL FENCE AROUND METERSHED, SEPARATOR SHED & TELEMETRY		

#### Equipment:

Type	#	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Deadman # & Marked	4	SATISFACTORY			

#### Venting:

Yes/No	Comment
NO	

#### Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 205369

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

**S/A/V:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****S/A/V:** \_\_\_\_\_ **Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 205369 Type: WELL API Number: 009-05050 Status: PR Insp. Status: PA

**Cement****Cement Contractor**

Contractor Name: BASIC ENERGY

Contractor Phone: \_\_\_\_\_

**Surface Casing**

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

**Intermediate Casing**

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

**Production Casing**

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

**Plugging Operations**

Depth Plugs(feet range): 4560

Cement Volume (sx): 150

Good Return During Job: \_\_\_\_\_

Cement Type: CLASS A

Comment: BLUE KNIGHT ENERGY PARTNERS, BASIC ENERGY SERVICES (CEMENTING AND COIL TUBING), C&J CASED HOLE SOLUTIONS. MIRU BASIC CT. RIH W/CT TO 4560' TO CLEAN OUT WELLBORE. POOH W/CT. WAIT ON WIRELINE FOR 2HRS. MIRU C&J. RIH W/GUN AND PERF @ 460'. MIRU BASIC CEMENTING AND DISP W/16BBL WATER DOWN TBG. MIRU BASIC CT AND RIH W/CT TO 4560' AND PUMP 100 SX CMT TBG PLUG AND DISP W/1BBL WATER. POOH W/CT. MIRU BASIC CEMENTING AND PUMP 25 SX CMT TBG PLUG @ 2500PSI AND DISP W/1BBL WATER. RU TO CSG AND PUMP 25 SX CMT CSG PLUG @ 500PSI.

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_

Inspector Name: Welsh, Brian

CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
Cuttings management: \_\_\_\_\_  
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

#### RESTORATION AND REVEGETATION

##### Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

##### Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation

#### **Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass  
Debris removed In No disturbance /Location never built \_\_\_\_\_  
Access Roads Regraded In Contoured In Culverts removed \_\_\_\_\_  
Gravel removed In  
Location and associated production facilities reclaimed In Locations, facilities, roads, recontoured In  
Compaction alleviation In Dust and erosion control \_\_\_\_\_  
Non cropland: Revegetated 80% In Cropland: perennial forage \_\_\_\_\_

Weeds present Pass Subsidence \_\_\_\_\_

Comment: **WELL IS PLUGGED. FENCE AND SURFACE EQUIPMENT STILL ON LOCATION**

Corrective Action: **CUT, CAP AND COVER WELLHEAD. REMOVE EQUIPMENT FOR FINAL RECLAMATION** Date **02/11/2015**

Inspector Name: Welsh, Brian

Overall Final Reclamation           In Process          

Well Release on Active Location ☐

Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass					

S/A/V: SATISFACTOR  
Y

Corrective Date:                     

Comment:

CA:

**Pits:** ☒ NO SURFACE INDICATION OF PIT

## **ACTION REQUIRED**

**ANY ACTION REQUIRED** items listed on this report indicate that the oil and gas facility or the oil and gas operations listed on the report may be in violation of the rules and regulations of the Colorado Oil and Conservation Commission (“COGCC”) and corrective action is required.

There is reasonable cause to believe that a violation of the Oil and Gas Conservation Act, or of any rule, regulation, or order of the Commission, or of any permit issued by the Commission, has occurred. The Operator’s compliance with this Inspection Report is required to resolve these alleged violations. This document requires the Operator to timely respond to the COGCC and to comply with directives as listed by the **Corrective Action Deadline Date**. Failure to do so will result in the issuance of a Notice of Alleged Violation and initiation of enforcement proceedings in which COGCC will seek monetary penalties for the alleged violations pursuant to § 34-60-121, C.R.S. and Rule 523, COGCC Rules of Practice and Procedure, 2 CCR 404-1. (Please note that the COGCC's penalty authority was recently increased to a maximum of \$15,000 per day and penalties are no longer capped at a maximum of \$10,000 per violation.)