


# Excell Services LLC, Christianson 22A-12

11/19/2015

IJ Well PA



11-19-2015 10:41



11.19.2015 10:42



11.19.2015 10:42

Pit at tank battery



11.19.2015 11:31

Tank battery in process  
flow line repair



11.19.2015 11:31