



Photo 1. View of kochia (*Kochia scoparia*) debris (approximately 3 feet tall) on working surface of the well pad. Kochia debris needs to be removed and properly disposed of.



Photo 2. View of musk thistles (*Carduus nutans*) growing within the southern portion of the interim reclamation area among cheatgrass (*Bromus tectorum*).





Photo 3. View of musk thistles within the northern portion of the interim reclamation area.





Photo 4. View of jointed goatgrass (*Aegilops cylindrica*) within the western portion of the interim reclamation area.



Photo 5. View of northwestern portion of the project area from mid-western edge facing northward. Grasses such as smooth brome (*Bromus inermis*), and western wheatgrass (*Pascopyron smithii*) as well as scattered big sagebrush (*Artemisia tridentata*) shrubs are growing here.





Photo 6. View of northern portion of project area from northwestern corner facing westward.