



Photo 1. Photo taken from Fairview Street, facing North. Access using this route needs to stop ASAP.



Photo 2. Photo taken from southern access road off CO 119. Need to control sediment leaving the area. Refer to photo #3.



Photo 3. Photo taken from CO 119, facing West. Sediment leaving area from access road onto CO 119. Need to control sediment leaving area as mud attached to vehicle tires.



Photo 4. Photo taken from northeast location, facing South. Stormwater BMP installed in center of photo.



Photo 5. Photo taken from southeast location, facing West. Stormwater BMP installed in center of photo.



Photo 6. Photo taken from west location, facing North. Stormwater BMP installed in center of photo.



Photo 7. Photo taken from eastern location, facing West. Topsoil stockpile in center of photo.