



Photo 1. View southern portion of the project area from southwestern corner facing eastward. Revegetation is largely outside of graveled berms and is largely comprised of intermediate wheatgrass (*Thinopyron intermedium*) and dropseed (*Sporobolus* sp.).



Photo 2. View of eastern portion of the project area from southeastern corner facing northward. An irrigation ditch runs adjacent to the eastern edge of the project area.



Photo 3. View of area in southwestern corner of project area that is starting to erode and needs to be monitored and BMPs applied if it worsens.



Photo 4. View of western edge of the project area from northwestern corner facing southward.



Photo 5. View of northern portion of project area from northwestern corner facing westward.