

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:
11/25/2015Document Number:
674300494Overall Inspection:
SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	261024	324169	Spencer, Stan	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 10163Name of Operator: NONSUCH NATURAL GAS INCAddress: P O BOX 110066City: NAPLES State: FL Zip: 34108

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Lee, David	239-289-9046	dlee@nng.us.com	
Mah, Steven		steven.mah@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Longworth, Mike		mike.longworth@state.co.us	
Edwards, Kent		kent.edwards@twaintheloop.com	
Nagy, Steve	303-796-2626	snagy@bflaw.com	
Lujan, Carlos		carlos.lujan@state.co.us	

Compliance Summary:QtrQtr: NENE Sec: 22 Twp: 6S Range: 97W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
10/08/2015	674300436	PR	PR	ALLEGED VIOLATION			Yes
08/03/2015	674300372	PR	PR	ALLEGED VIOLATION			Yes
09/28/2010	1949076	ES	PR	ACTION REQUIRED			
07/28/2010	1949072	CO	PR	ACTION REQUIRED			Yes
09/30/2009	200219090	CO	PR	ACTION REQUIRED			Yes
11/10/2008	200198278	PR	PR	ACTION REQUIRED	I		Yes
09/01/2008	200206565	PR	PR	SATISFACTORY			No
07/25/2008	200192844	PR	PR	ACTION REQUIRED	I		Yes
06/12/2008	200195268	PR	WO	ACTION REQUIRED	I		Yes
06/13/2007	200117613	PR	PR	ACTION REQUIRED			Yes
07/07/2005	200076106	PR	PR	SATISFACTORY		Pass	No
08/22/2002	200032794	PR	PR	SATISFACTORY		Pass	No

Inspector Comment:

Net installed in compliance with NOAV warning letter. Net is properly properly installed and appears to be new. Fluid levels in pit are low and partially frozen over. F-4 Sundry documenting this corrective action has been approved. See attached photos.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
261024	WELL	PR	08/17/2001	GW	045-07928	CSOC 697-22 1	PR	<input type="checkbox"/>
292475	PIT	AC	09/27/2007		-	CSOC 697-22 1	AC	<input type="checkbox"/>
324169	LOCATION	AC	04/14/2009		-	CSOC 697-22-66S97W 22NENE	AC	<input type="checkbox"/>
418328	PIT		07/16/2010		-	DANISH FLATS		<input type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/A/V): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Venting:**

Yes/No	Comment

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 261024

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 0 Type: _____ API Number: - Status: _____ Insp. Status: _____

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: 0

Comment: _____

Corrective Action: Net installed in compliance with NOAV warning letter. Net is properly properly installed Date: 11/25/2015

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Inspector Name: Spencer, Stan

DWR Receipt Num:	Owner Name:	GPS :	Lat	Long
Field Parameters:				
Sample Location: _____				
Emission Control Burner (ECB): _____				
Comment: _____				
Pilot: _____ Wildlife Protection Devices (fired vessels): _____				

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	418328	2607827	
	292475	400784065	
	292475	1433719	
	292475	400784065	

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674300495	pit with newly installed net lookin S	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3730592
674300496	pit with newly installed net lookin NE	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3730593