

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
12/03/2015

Document Number:
679700103

Overall Inspection:
SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	<input type="checkbox"/>
	245869	326782	ALLISON, RICK	2A Doc Num:	

Operator Information:

OGCC Operator Number:	<u>88380</u>
Name of Operator:	<u>TINDALL OPERATING COMPANY</u>
Address:	<u>12741 E CALEY STE 142</u>
City:	<u>CENTENNIAL</u> State: <u>CO</u> Zip: <u>80111</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Lee Tucker		rleetuck@aol.com	

Compliance Summary:

QtrQtr: SWNE Sec: 13 Twp: 7N Range: 59W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
07/16/2015	680300087	SI	SI	SATISFACTORY			No
06/01/2015	668303605	PR	PR	ACTION REQUIRED			No
12/15/2009	200225641	PR	PR	ACTION REQUIRED			Yes
05/19/2003	200039233	PR	PR	SATISFACTORY		Pass	No
04/15/2003	200037585	PR	PR	ACTION REQUIRED		Fail	Yes
01/17/2001	200013606	PR	PR	SATISFACTORY	I	Pass	No

Inspector Comment:

COGCC followup inspection to pit closure, and tank battery closure - Remediation Project #9151

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
111640	PIT				-	LIND 3	EI	<input checked="" type="checkbox"/>
111641	PIT				-	LIND 5	EI	<input checked="" type="checkbox"/>
245869	WELL	SI	05/31/2015	OW	123-13664	LIND 3	EI	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/A/V): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 245869

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 111640 Type: PIT API Number: - Status: _____ Insp. Status: EI

Facility ID: 111641 Type: PIT API Number: - Status: _____ Insp. Status: EI

Facility ID: 245869 Type: WELL API Number: 123-13664 Status: SI Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Waste Management:

Type	Management	Condition	Comment	GPS (Lat)	(Long)
Oily Soil	Other	Adequate	It appears that excavated oily waste has been removed from the location. Clean soil is stockpiled pending backfill of pits.		

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
 Land Use: _____
 Comment: _____

1003a. Debris removed? _____ CM _____ CA _____ CA Date _____
 Waste Material Onsite? _____ CM _____ CA _____ CA Date _____
 Unused or unneeded equipment onsite? _____ CM _____ CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? _____ CM _____ CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____ CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____ CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location

Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

Pit Type: Produced Water Lined: Pit ID: 111641 Lat: 40.572806 Long: -103.919036

Lining:

Liner Type: Liner Condition:

Comment:

Fencing:

Fencing Type: Fencing Condition:

Comment:

Netting:

Netting Type: Netting Condition:

Comment:

Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard:

Pit (S/A/V): Comment: Pit closure in progress; submit waste disposal documentation and confirmation soil samples collected in accordance with the Conditions of Approval for Remediation Project #9151 for COGCC review and approval prior to backfill. Pit has been overexcavated so a minimum of one confirmation soil sample must be collected from each sidewall and the base of the excavation of the produced water pit

Corrective Action: Date:

Pit Type: Skimming/Settling Lined: Pit ID: 111640 Lat: 40.576486 Long: -103.918936

Lining:

Liner Type: Liner Condition:

Comment:

Fencing:

Fencing Type: Fencing Condition:

Comment:

Netting:

Netting Type: Netting Condition:

Comment:

Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard:

Pit (S/A/V): Comment: Pit closure in progress; submit waste disposal documentation and confirmation soil samples collected in accordance with the Conditions of Approval for Remediation Project #9151 for COGCC review and approval prior to backfill. Pit has been overexcavated so a minimum of one confirmation soil sample must be collected from each sidewall and the base of the excavation of the skim pit

Corrective Action: Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679700108	Excavated skim pit looking south	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3733614
679700109	South wall excavated produced water pit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3733615
679700110	Produced water pit looking south	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3733616
679700111	From NE corner PW pit looking SE toward skim pit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3733617