



photo 1: Facing west towards the beginning of the former access road.



photo 2: Facing back west at the beginning of the former access road where gravel has not been removed.



photo 3: Facing west along the former access road.



photo 4: Facing west towards the location..



Photo 5: Center of the location facing north.



photo 6: Center of the location facing west.



photo 7: Center of the location facing south.



photo 8: Center of the location facing east.



photo 9: Close up of vegetation cover which is predominately weeds (kochia, russian thistle).



photo 10: Surrounding vegetation growth, reference area.