



**Photo 1.** Photo taken from southern location, facing West. Operator installed cobble along entire access road to the pad.



**Photo 2.** Photo taken from southwest location, facing North. Operator installed cobble along entire access road to the pad.



**Photo 3.** Photo taken from Fairview Street, facing North. Operator blocked traffic access from Fairview Street onto the location.



**Photo 4.** Photo taken from northern location, facing East. The northern proposed tank battery location still under construction. Upon completion, all soil piles shall be stabilized to prevent soil erosion.



**Photo 5.** Photo taken from northern location, facing East. Soil pile located just north of the main pad. The northern proposed tank battery location is still under construction. Upon completion, all soil piles shall be stabilized to prevent soil erosion.