



Photo 1. Photo taken of well sign.



Photo 2. Photo taken from northern location, facing South. Weeds need to be removed from around the well per Rule 603.f. Interim reclamation success can not be evaluated until the next growing season.



Photo 3. Photo taken from western location, facing East. Weeds need to be removed from around the well per Rule 603.f. Interim reclamation success can not be evaluated until the next growing season.




Photo 4. Photo taken from southern location, facing North. Weeds need to be removed from around the well per Rule 603.f. Interim reclamation success can not be evaluated until the next growing season.



Photo 5. Photo taken from eastern location, facing West. Weeds need to be removed from around the well per Rule 603.f. Interim reclamation success can not be evaluated until the next growing season.