

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
12/03/2015

Document Number:
682600038

Overall Inspection:

ACTION REQUIRED

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>413110</u>	<u>413089</u>	<u>Kosola, Jason</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>96340</u>
Name of Operator:	<u>WIEPKING-FULLERTON ENERGY LLC</u>
Address:	<u>4600 S DOWNING ST</u>
City:	<u>ENGLEWOOD</u> State: <u>CO</u> Zip: <u>80113</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Boone, Linda		LDBoonePar@aol.com	all inspections
Fincham, Jack		fincham4@msn.com	all inspections
Weipking, Jeff	(303) 789-1798	jwiepking@msn.com	All Inspections
Trujillo, Aaron		aaron.trujillo@state.co.us	

Compliance Summary:

QtrQtr: SWNE Sec: 19 Twp: 10S Range: 55W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
11/20/2014	673501873	DA	DA	ACTION REQUIRED		Fail	No
08/06/2012	663901466	DA	DA	ACTION REQUIRED		I	No

Inspector Comment:

COGCC Environmental Field Report to investigate and document suspected surface impacts visible on aerial photographs.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
413110	WELL	DA	07/16/2010	OW	073-06389	ALOHA MULA 6	DA <input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: <u>1</u>	Wells: <u>1</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>6</u>	Separators: <u>6</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: <u>1</u>
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: <u>11</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/A/V): ACTION

Corrective Date: 12/22/2015

Inspector Name: Kosola, Jason

Comment: COGCC phoned the emergency contact number listed on sign. Phone was not answered by live attendant and voice mailbox was incapable of receiving messages.

Corrective Action: Correct sign or otherwise ensure that emergency number will allow a live representative of the operator to be reached at all times, pursuant to Rule 605.c.(4).

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

Multiple Spills and Releases?

Venting:

Yes/No	Comment
--------	---------

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
------	------------------------------	---------	-------------------	---------

Predrill

Location ID: 413110

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Group	User	Comment	Date
Agency	ashm	Conducted field visit on July 17, 2009.	07/28/2009

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

BMP Type	Comment
PROPOSED BMPs	<p>Wiepking- Fullerton Energy, L.L.C.</p> <p>4600 S. Downing St.</p> <p>Englewood, CO 80113</p> <p>303 - 789 -1798</p> <p>303 - 761 -9067 (fax)</p> <p>Certification to Discharge</p> <p>Under</p> <p>CDPS General Permit COR -03000</p> <p>Stormwater Discharges Associated with Construction</p> <p>Certification Number COR 39788</p> <p>IIII1111Iiit IIllll111111</p> <p>2097E</p> <p>Description of Well Site and Construction Area</p> <p>1 -3 acre site with access road for drilling of oil and gas well. Terrain is flat with native grass and sagebrush. No receiving waters will be affected by well pad. Drilling pits closed and reclaimed with the drillsite, reseeded within 6 months weather permitting. Silt fences will be installed on low side site of drill site. Topsoil will be separated and spread on drill site as final operation before reseeding operations. To prevent soil erosion site will be disked and straw crimped in or manure spread.</p> <p>Stormwater Management Plan (SWMP) is on file in Wiepking - Fullerton Energy, L.L.C. office.</p> <p>Spill Prevention, Control and Countermeasure Plan is on file in Wiepking- Fullerton Energy, L.L.C. office.</p>

S/A/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Inspector Name: Kosola, Jason

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____
 Request LGD Attendance: _____
LGD Contact Information:
 Name: _____ Phone Number: _____ Agreed to Attend: _____
Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 413110 Type: WELL API Number: 073-06389 Status: DA Insp. Status: DA

Environmental

Spills/Releases:
 Type of Spill: DRILLING Description: Drilling mud Estimated Spill Volume: 868
 Comment: Drilling fluid released from drill pad covering approximately 0.7 acres of native vegetation. Native grasses killed off within release area. Little to no regrowth of native vegetation from last growing season was observed. This inspection documented that fluids were not incorporated into native soils. Spill volume estimated based on area of spill.
 Corrective Action: SEE INSPECTION COMMENTS ON PAGE 5:Spill/release corrective action:Operator Date: 02/08/2016
 Reportable: YES GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:
 Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
 Land Use: RANGELAND
 Comment: _____
 1003a. Debris removed? _____ CM _____
 CA _____ CA Date _____
 Waste Material Onsite? _____ CM _____
 CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____
 Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>Spill/release corrective action: Operator must submit Form 19 spill report documenting unauthorized release of drilling fluids by 12-31-2015. Operator must submit Form 27 with confirmation soil sample results verifying that the drilling mud disposed of on surface complies with Table 910-1 standards. Operator must also provide confirmation samples from the pit that verifies pit contents comply with Table 910-1.</p> <p>If operator did not obtain samples from drilling pit prior to closure then samples must be collected by a qualified person. Samples shall be collected from any residual E&P waste in pit and from native soil at base of pit.</p> <p>If sample results verify compliance with Table 910-1 standards, then operator must incorporate material into native soil and reclaim the surface in accordance with Rule 1003. Do not incorporate without COGCC prior approval.</p> <p>Please notify COGCC when sampling will be conducted.</p>	kosolaj	12/08/2015

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682600039	Aerial photo map	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3735800
682600040	Inspection pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3735801

ACTION REQUIRED

ANY ACTION REQUIRED items listed on this report indicate that the oil and gas facility or the oil and gas operations listed on the report may be in violation of the rules and regulations of the Colorado Oil and Conservation Commission (“COGCC”) and corrective action is required.

There is reasonable cause to believe that a violation of the Oil and Gas Conservation Act, or of any rule, regulation, or order of the Commission, or of any permit issued by the Commission, has occurred. The Operator’s compliance with this Inspection Report is required to resolve these alleged violations. This document requires the Operator to timely respond to the COGCC and to comply with directives as listed by the **Corrective Action Deadline Date**. Failure to do so will result in the issuance of a Notice of Alleged Violation and initiation of enforcement proceedings in which COGCC will seek monetary penalties for the alleged violations pursuant to § 34-60-121, C.R.S. and Rule 523, COGCC Rules of Practice and Procedure, 2 CCR 404-1. (Please note that the COGCC's penalty authority was recently increased to a maximum of \$15,000 per day and penalties are no longer capped at a maximum of \$10,000 per violation.)