

LEGEND

- * PHOTO
- ONSITE SAMPLE
- ▲ OFFSITE SAMPLE
- RECLAMATION AREA
- LONG TERM DISTURBANCE
- ACCESS ROAD




IMAGE COURTESY OF ESRI

RECLAMATION AREA: 3.28 ACRES
LONG TERM DISTURBANCE AREA: 1.44 ACRES

RECLAMATION MONITORING MAP
NON-BLM LAND
GIBSON GULCH UNIT 1-30
GARFIELD COUNTY, COLORADO

VANGUARD OPERATING, LLC





Onsite North



Onsite East



Onsite South



Onsite West

Photos Taken: 08/07/2015

Gibson Gulch Unit 1-30

Site Photographs



Offsite North



Offsite East



Offsite South



Offsite West

Photos Taken: 08/07/2015

Gibson Gulch Unit 1-30

Site Photographs