

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:

12/10/2015

Document Number:

674702175

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	335822	335822	LONGWORTH, MIKE	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, General	970-285-2665	cogcc.inspections@encana.com	EnCana Inspection email

Compliance Summary:QtrQtr: NWNW Sec: 28 Twp: 5S Range: 95W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
12/31/2014	674700815			SATISFACTORY			No
12/30/2013	663902575			SATISFACTORY			No
12/30/2013	663902576			SATISFACTORY			No

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
281942	WELL	PR	04/05/2007	GW	045-11587	N. PARACHUTE EF04D D28 595	PR
281943	WELL	PR	02/01/2014	GW	045-11588	N. PARACHUTE EF05B D28 595	PR
282068	WELL	PR	02/01/2011	GW	045-11626	N. PARACHUTE EF14B D28 595	PR
282069	WELL	PR	04/05/2007	GW	045-11625	N. PARACHUTE EF12D D28 595	PR
282070	WELL	PR	04/05/2007	GW	045-11624	N. PARACHUTE EF13B D28 595	PR
282071	WELL	PR	04/05/2007	GW	045-11623	N. PARACHUTE EF04B D28 595	PR
282085	WELL	PR	04/05/2007	GW	045-11634	N. PARACHUTE EF13D D28 595	PR
285097	WELL	PR	04/05/2007	GW	045-12377	N. PARACHUTE EF05D D28 595	PR
297249	WELL	AL	07/07/2011	LO	045-16352	N. PARACHUTE EF04B-28 D28 59	AL

Inspector Name: LONGWORTH, MIKE

297250	WELL	AL	07/07/2011	LO	045-16353	N. PARACHUTE EF03C-28 D28 59	AL	<input checked="" type="checkbox"/>
297251	WELL	AL	06/23/2011	LO	045-16354	N. PARACHUTE EF04C-28 D28 59	AL	<input checked="" type="checkbox"/>
297252	WELL	AL	07/07/2011	LO	045-16355	N. PARACHUTE EF12C-21 D28 59	AL	<input checked="" type="checkbox"/>
297255	WELL	AL	07/07/2011	LO	045-16358	N. PARACHUTE EF13A-21 D28 59	AL	<input checked="" type="checkbox"/>
297257	WELL	AL	04/01/2009	LO	045-16359	N. PARACHUTE EF13C-21 D28 59	AL	<input checked="" type="checkbox"/>
297258	WELL	AL	07/07/2011	LO	045-16360	N. PARACHUTE EF14A-21 D28 59	AL	<input checked="" type="checkbox"/>
297259	WELL	AL	07/07/2011	LO	045-16361	N. PARACHUTE EF14C-21 D28 59	AL	<input checked="" type="checkbox"/>
297260	WELL	AL	06/23/2011	LO	045-16362	N. PARACHUTE EF08C-20 D28 59	AL	<input checked="" type="checkbox"/>
297261	WELL	AL	07/07/2011	LO	045-16363	N. PARACHUTE EF09B-20 D28 59	AL	<input checked="" type="checkbox"/>
297262	WELL	AL	06/22/2011	LO	045-16364	N. PARACHUTE EF09C-20 D28 59	AL	<input checked="" type="checkbox"/>
297263	WELL	AL	06/23/2011	LO	045-16365	N. PARACHUTE EF08D-20 D28 59	AL	<input checked="" type="checkbox"/>
297264	WELL	AL	06/23/2011	LO	045-16366	N. PARACHUTE EF12A-21 D28 59	AL	<input checked="" type="checkbox"/>
297265	WELL	AL	06/23/2011	LO	045-16367	N. PARACHUTE EF16B-20 D28 59	AL	<input checked="" type="checkbox"/>
297789	WELL	AL	06/23/2011	LO	045-16963	N. PARACHUTE EF11D-21 D28 59	AL	<input checked="" type="checkbox"/>
297791	WELL	AL	06/23/2011	LO	045-16965	N. PARACHUTE EF11B-21 D28 59	AL	<input checked="" type="checkbox"/>
425763	PIT	CL	02/26/2015		-	EF D28 595	CL	<input type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/A/V): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 335822

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 297249 Type: WELL API Number: 045-16352 Status: AL Insp. Status: AL

Facility ID: 297250 Type: WELL API Number: 045-16353 Status: AL Insp. Status: AL

Inspector Name: LONGWORTH, MIKE

Facility ID:	297251	Type:	WELL	API Number:	045-16354	Status:	AL	Insp. Status:	AL
Facility ID:	297252	Type:	WELL	API Number:	045-16355	Status:	AL	Insp. Status:	AL
Facility ID:	297255	Type:	WELL	API Number:	045-16358	Status:	AL	Insp. Status:	AL
Facility ID:	297257	Type:	WELL	API Number:	045-16359	Status:	AL	Insp. Status:	AL
Facility ID:	297258	Type:	WELL	API Number:	045-16360	Status:	AL	Insp. Status:	AL
Facility ID:	297259	Type:	WELL	API Number:	045-16361	Status:	AL	Insp. Status:	AL
Facility ID:	297260	Type:	WELL	API Number:	045-16362	Status:	AL	Insp. Status:	AL
Facility ID:	297261	Type:	WELL	API Number:	045-16363	Status:	AL	Insp. Status:	AL
Facility ID:	297262	Type:	WELL	API Number:	045-16364	Status:	AL	Insp. Status:	AL
Facility ID:	297263	Type:	WELL	API Number:	045-16365	Status:	AL	Insp. Status:	AL
Facility ID:	297264	Type:	WELL	API Number:	045-16366	Status:	AL	Insp. Status:	AL
Facility ID:	297265	Type:	WELL	API Number:	045-16367	Status:	AL	Insp. Status:	AL
Facility ID:	297789	Type:	WELL	API Number:	045-16963	Status:	AL	Insp. Status:	AL
Facility ID:	297791	Type:	WELL	API Number:	045-16965	Status:	AL	Insp. Status:	AL

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment: _____
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Inspector Name: LONGWORTH, MIKE

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: 8 producing wells on location. No evidence on AL wells on location.

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Pass _____

Well Release on Active Location ☒

Multi-Well Location ☒

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT