

## Ptasynski 1X

Inspection# 673402723

No bird protectors apparent  
on separator. Separator less  
than 20 feet from wellhead.

12/3/2015

Inspection 673402723



Pit

12/3/2015

Inspection 673402723

