



photo 1: Facing east along former access road towards the location.



photo 2: Facing southeast along former access road towards the location.



photo 3: Facing southeast along former access road towards the location.



photo 4: Facing southeast towards the location.



Photo 5: Center of the location facing north.



photo 6: Center of the location facing west.



photo 7: Center of the location facing south.



photo 8: Center of the location facing east.



photo 9: Photo of the groundcover and soil condition.




photo 10: Weed growth (kochia) is the predominate vegetation cover throughout the location.



photo 11: West side of the location facing east at the location.



photo 12: Northeast corner of the location facing southwest.



photo 13: Facing northwest.



photo 14: Surrounding vegetation, reference area.