

## Ptasynski 4

Inspection# 673402734

Pit.

12/8/2015

Inspection 673402734



No tank label, insulation  
blowing off of tank.

12/8/2015

Inspection 673402734

