

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
12/09/2015

Document Number:
680600406

Overall Inspection:

ACTION REQUIRED

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>293876</u>	<u>333966</u>	<u>ROY, CATHERINE</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number:	<u>19160</u>
Name of Operator:	<u>CONOCO PHILLIPS COMPANY</u>
Address:	<u>P O BOX 2197</u>
City:	<u>HOUSTON TX</u> State: <u>TX</u> Zip: <u>77252-</u>

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Busse, Dollie	505-324-6104	Dollie.L.Busse@conocophillips.com	All SW Inspections
Notor, Lori		Lori.R.Notor@conocophillips.com	SW Inspections
Walker, Crystal		Crystal.Walker@conocophillips.com	All Inspections

Compliance Summary:

QtrQtr:	<u>SENE</u>	Sec:	<u>32</u>	Twp:	<u>34N</u>	Range:	<u>9W</u>
---------	-------------	------	-----------	------	------------	--------	-----------

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
01/21/2014	667700213	PR	PR	SATISFACTORY	P		No
03/12/2013	669400480	PR	PR	SATISFACTORY	I		No
06/03/2010	200253153	PR	PR	SATISFACTORY			No

Inspector Comment:

This is an interim reclamation and stormwater inspection. Any corrective actions from previous inspection not addressed are still applicable.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
258709	WELL	PR	02/01/2011	GW	067-08375	BALANTINE 34-9 32-4	PR	<input checked="" type="checkbox"/>
293876	WELL	PR	02/01/2011	GW	067-09461	BALLANTINE 34-9 32-2A	PR	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/A/V): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 293876

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AV: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 258709 Type: WELL API Number: 067-08375 Status: PR Insp. Status: PR

Facility ID: 293876 Type: WELL API Number: 067-09461 Status: PR Insp. Status: PR

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: **The outer portions of the interim reclamation area appear to be in agricultural use. There are thousands of jointed goatgrass growing along the edges of the project area. Jointed goatgrass is a State and County-listed noxious weed. Additionally kochia debris needs to be removed.**

1003a. Debris removed? Fail CM Weed debris along the edges of the workign area.

CA Removed weed debris. CA Date 01/15/2016

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? In Production areas stabilized ? In

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

Inspector Name: ROY, CATHERINE

1003 f. Weeds Noxious weeds? F

Comment: Noxious weeds need to be controlled at the appropriate time but no later than seedhead maturity in 2016 (spring).

Overall Interim Reclamation Fail

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: Date Final Reclamation Completed:

Final Land Use:

Reminder:

Comment:

Well plugged Pit mouse/rat holes, cellars backfilled

Debris removed No disturbance /Location never built

Access Roads Regraded Contoured Culverts removed

Gravel removed

Location and associated production facilities reclaimed Locations, facilities, roads, recontoured

Compaction alleviation Dust and erosion control

Non cropland: Revegetated 80% Cropland: perennial forage

Weeds present Subsidence

Comment:

Corrective Action: Date

Overall Final Reclamation Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: SATISFACTOR Corrective Date:
Y

Comment: Stormwater erosion appears to be controlled on the location at this time.

CA:

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Location does not meet reclamation regulations. Noxious weeds need to be controlled no later than seedhead maturity in 2016 (spring). Weed debris needs to be removed by January 15, 2016.	RoyC	12/16/2015

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680600407	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3742276

ACTION REQUIRED

ANY ACTION REQUIRED items listed on this report indicate that the oil and gas facility or the oil and gas operations listed on the report may be in violation of the rules and regulations of the Colorado Oil and Conservation Commission (“COGCC”) and corrective action is required.

There is reasonable cause to believe that a violation of the Oil and Gas Conservation Act, or of any rule, regulation, or order of the Commission, or of any permit issued by the Commission, has occurred. The Operator’s compliance with this Inspection Report is required to resolve these alleged violations. This document requires the Operator to timely respond to the COGCC and to comply with directives as listed by the **Corrective Action Deadline Date**. Failure to do so will result in the issuance of a Notice of Alleged Violation and initiation of enforcement proceedings in which COGCC will seek monetary penalties for the alleged violations pursuant to § 34-60-121, C.R.S. and Rule 523, COGCC Rules of Practice and Procedure, 2 CCR 404-1. (Please note that the COGCC's penalty authority was recently increased to a maximum of \$15,000 per day and penalties are no longer capped at a maximum of \$10,000 per violation.)