

Reclamation Follow-up Inspection

12/11/2015

Operator: Bonanza Creek Operating

Location ID: 431387

Weld County, CO

NWNW Section 10 T5N R61W

Aaron Trujillo

Reclamation Specialist

COGCC



12.11.2015 14:12

Figure 1: Photo taken from southwest end of location facing northeast. Photo shows weed debris has been removed.



Figure 2: Photo taken from the southwest end of location, facing north. Photo shows weed debris has been removed.



Figure 3: Photo taken from southwest end of location, facing east. Photo shows weed debris has been removed.



Figure 4: Photo taken from northeast end of location, facing south. Photo shows weed debris has been removed.



Figure 5: Photo taken from northeast end of location, facing west. Photo shows weed debris has been removed.