



Photo 1. View from dry hole marker for 083-06388 on well pad facing northward. Stockpile of unknown material, approximately 8 feet tall and 70 feet long is present in the background.



Photo 2. View of musk thistle (*Carduus nutans*) on well pad. Musk thistle needs to be controlled.



Photo 3. View of bull thistle (*Cirsium vulgare*) plants growing on the well pad. Bull thistle needs to be controlled.



Photo 4. View of vehicle turnaround area on well pad surface. This area needs to be de-compacted to 18 inches and revegetated.



Photo 5. View of revegetation within the eastern portion of the project area. Dense grasses and forbs such as smooth brome (*Bromus inermis*), western wheatgrass (*Pascopyrum smithii*), and yellow sweetclover (*Melilotus officinalis*) are growing here.