



**Overview of Location, looking North.**

Photo#1:

December 6, 2015

Inspection Photos Whiting Oil Loc #  
336040



**View to NE overlooking Pad Area**

Photo#2:

December 6, 2015

Inspection Photos Whiting Oil Loc #  
336040



**Material Piles on Location.**

Photo#3:

December 6, 2015

Inspection Photos Whiting Oil Loc #  
336040



**Gravel Stock Pile on Location.**

Photo#4:

December 6, 2015

Inspection Photos Whiting Oil Loc #  
336040



**Concrete Debris on Location.**

Photo#5:

December 6, 2015

Inspection Photos Whiting Oil Loc #  
336040



**View SW overlooking Pad area.**

Photo#6:

December 6, 2015

Inspection Photos Whiting Oil Loc #  
336040



**Access Road into Location.**

Photo#6

December 6, 2015

Inspection Photos Whiting Oil Loc #  
336040