



Photo#1: View of Location from Entrance.



Photo#2: View NW.





Photo#3: Fenced Interim Reclamation area



Photo#4: Newly Installed Drainage Area BMPs .





Photo#5: Retention Pond