

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

DE	ET	OE	ES
----	----	----	----

Inspection Date:
12/06/2015Document Number:
680100379Overall Inspection:
SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	290936	335891	Colby, Lou	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 96155Name of Operator: WHITING OIL & GAS CORPORATIONAddress: 1700 BROADWAY STE 2300City: DENVER State: CO Zip: 80290

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
D'hooge, John	303-390-4222	johnd@whiting.com	
Mezydlo, Cara	303-876-7091	cara.mezydlo@whiting.com	

Compliance Summary:QtrQtr: SESE Sec: 19 Twp: 2S Range: 97W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/27/2015	673402086	AL	AL	SATISFACTORY			No

Inspector Comment:

This is an Abandoned Location inspection for Wells API#s 103- 11031, 11076, 11107,11108,11110,11112, 11442,11443. It does not appear that these Wells (AL) were drilled on the location with producing wells 103-11030, 11034,11035, 11067, 11109, 11111; therefore, this Inspection is for Well releases on an Active Location. Permits for these Wells expired 7/16/09, Abandoned 8/1/11.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
290936	WELL	AL	08/09/2011	LO	103-11031	BOIES B-19P-02	AL	<input checked="" type="checkbox"/>
290938	WELL	PR	11/25/2008	GW	103-11030	BOIES B-19P-30A1	PR	<input type="checkbox"/>
291112	WELL	PR	10/24/2008	GW	103-11034	BOIES B-19P-P3	PR	<input type="checkbox"/>
291117	WELL	PR	06/18/2009	GW	103-11035	BOIES B-19P-30A3	PR	<input type="checkbox"/>
291947	WELL	PR	05/28/2014	GW	103-11067	BOIES B-19P-03	PR	<input type="checkbox"/>
291982	WELL	AL	08/09/2011	LO	103-11076	BOIES B-19P-P2	AL	<input checked="" type="checkbox"/>
293251	WELL	AL	08/09/2011	LO	103-11107	BOIES B-19P-04	AL	<input checked="" type="checkbox"/>
293252	WELL	AL	08/09/2011	LO	103-11108	BOIES B-19P-30A2	AL	<input checked="" type="checkbox"/>
293253	WELL	PR	05/28/2014	GW	103-11109	BOIES B-19P-O1	PR	<input type="checkbox"/>

Inspector Name: Colby, Lou

293254	WELL	AL	08/09/2011	LO	103-11110	BOIES B-19P-P4	AL	<input checked="" type="checkbox"/>
293255	WELL	PR	05/28/2014	GW	103-11111	BOIES B-19P-P1	PR	<input type="checkbox"/>
293256	WELL	AL	08/09/2011	LO	103-11112	BOIES B-19P-30A4	AL	<input checked="" type="checkbox"/>
300418	WELL	AL	08/09/2011	LO	103-11442	BOIES A-19P-20M3	AL	<input checked="" type="checkbox"/>
300419	WELL	AL	08/09/2011	LO	103-11443	BOIES A-19P-29D1	AL	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/A/V): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Predrill

Location ID: 290936

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:**S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****S/A/V:** _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 290936 Type: WELL API Number: 103-11031 Status: AL Insp. Status: AL

Facility ID: 291982 Type: WELL API Number: 103-11076 Status: AL Insp. Status: AL

Facility ID: 293251 Type: WELL API Number: 103-11107 Status: AL Insp. Status: AL

Facility ID: 293252 Type: WELL API Number: 103-11108 Status: AL Insp. Status: AL

Facility ID: 293254 Type: WELL API Number: 103-11110 Status: AL Insp. Status: AL

Facility ID: 293256 Type: WELL API Number: 103-11112 Status: AL Insp. Status: AL

Inspector Name: Colby, Lou

Facility ID: 300418	Type: WELL	API Number: 103-11442	Status: AL	Insp. Status: AL
Facility ID: 300419	Type: WELL	API Number: 103-11443	Status: AL	Insp. Status: AL

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

Inspector Name: Colby, Lou

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Pass _____ Well Release on Active Location ☒ Multi-Well Location ☒

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: SATISFACTOR _____ Corrective Date: _____

Y

Comment: _____

CA: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images ([https://cogcc.state.co.us/weblink/](https://cogcc.state.co.us/webblink/)) and search by document number:

Inspector Name: Colby, Lou

Document Num	Description	URL
680100380	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3746189