



**photo 1:** Facing west along the access road towards the location.



**photo 2:** Facing southwest along the access road towards the location.



**photo 3:** Facing southwest towards the location.



**photo 4:** Facing south towards the location.



**Photo 5:** Sediment trap has been maintained.



**Photo 6:** Facing towards the southwest side of the location.