

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/23/2015

Document Number:

666801768

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	294181	335484	Murray, Richard	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 96850Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@wpxenergy.com	Field Inspections

Compliance Summary:QtrQtr: NESW Sec: 13 Twp: 6S Range: 94W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/03/2011	200302443	SR	PR	SATISFACTORY			No
07/02/2010	200263225	SR	PR	ACTION REQUIRED			No
06/22/2010	200277487	PR	PR	SATISFACTORY			No
02/25/2010	200232614	PR	PR	SATISFACTORY			No

Inspector Comment:Inspection if for wells with the status of Abandoned Location**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
294180	WELL	AL	05/27/2011	LO	045-15299	CLOUGH RWF 324-13	AL	<input checked="" type="checkbox"/>
294181	WELL	PR	08/01/2008	GW	045-15300	CLOUGH RWF 424-13	PR	<input type="checkbox"/>
294182	WELL	PR	08/30/2008	GW	045-15301	CLOUGH RWF 24-13	PR	<input type="checkbox"/>
294183	WELL	AL	05/27/2011	LO	045-15302	CLOUGH RWF 513-13	AL	<input checked="" type="checkbox"/>
294184	WELL	AL	05/27/2011	LO	045-15303	CLOUGH RWF 413-13	AL	<input checked="" type="checkbox"/>
294185	WELL	AL	05/27/2011	LO	045-15304	CLOUGH RWF 313-13	AL	<input checked="" type="checkbox"/>
294186	WELL	AL	05/27/2011	LO	045-15305	CLOUGH RWF 13-13	AL	<input checked="" type="checkbox"/>
294187	WELL	AL	05/27/2011	LO	045-15306	CLOUGH RWF 314-13	AL	<input checked="" type="checkbox"/>

Inspector Name: Murray, Richard

294188	WELL	AL	05/27/2011	LO	045-15307	CLOUGH RWF 414-13	AL	<input checked="" type="checkbox"/>
294189	WELL	AL	05/27/2011	LO	045-15308	CLOUGH RWF 514-13	AL	<input checked="" type="checkbox"/>
294190	WELL	PR	08/01/2008	GW	045-15309	CLOUGH RWF 23-13	PR	<input type="checkbox"/>
294191	WELL	AL	05/27/2011	LO	045-15310	CLOUGH RWF 323-13	AL	<input checked="" type="checkbox"/>
294192	WELL	AL	05/27/2011	LO	045-15311	CLOUGH RWF 423-13	AL	<input checked="" type="checkbox"/>
294193	WELL	AL	05/27/2011	LO	045-15312	CLOUGH RWF 523-13	AL	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number (S/AR): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:

Yes/No	
Comment	

Flaring:

Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 294181

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Data retrieval failed for the subreport 'Subreport1' located at: \\10.12.100.15\FarmReports\Insp\InspCOA.rdl. Please check t

S/AR: _____ **Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:**

Data retrieval failed for the subreport 'Subreport2' located at: \\10.12.100.15\FarmReports\Insp\InspBMP.rdl. Please check t

S/AR: _____ **Comment:** _____**CA:** _____ **Date:** _____**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 294180 Type: WELL API Number: 045-15299 Status: AL Insp. Status: AL

Facility ID: 294183 Type: WELL API Number: 045-15302 Status: AL Insp. Status: AL

Facility ID: 294184 Type: WELL API Number: 045-15303 Status: AL Insp. Status: AL

Facility ID: 294185 Type: WELL API Number: 045-15304 Status: AL Insp. Status: AL

Facility ID: 294186 Type: WELL API Number: 045-15305 Status: AL Insp. Status: AL

Inspector Name: Murray, Richard

Facility ID:	294187	Type:	WELL	API Number:	045-15306	Status:	AL	Insp. Status:	AL
Facility ID:	294188	Type:	WELL	API Number:	045-15307	Status:	AL	Insp. Status:	AL
Facility ID:	294189	Type:	WELL	API Number:	045-15308	Status:	AL	Insp. Status:	AL
Facility ID:	294191	Type:	WELL	API Number:	045-15310	Status:	AL	Insp. Status:	AL
Facility ID:	294192	Type:	WELL	API Number:	045-15311	Status:	AL	Insp. Status:	AL
Facility ID:	294193	Type:	WELL	API Number:	045-15312	Status:	AL	Insp. Status:	AL

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

The subreport 'rptInsp13' could not be found at the