

Interim Reclamation Inspection

Inspection Date: 12/22/2015

Operator: Noble Energy Inc.

Location ID: 422413

API #: 05-123-33238

Weld County, CO

SESE Section 27 T9N R59W

Aaron Trujillo
Reclamation Specialist
COGCC



Figure 1: Photo of sign at well.



Figure 2: Photo taken from northwest end of location, facing east. Photo of interim reclamation.



Figure 3: Photo taken from northwest end of location, facing southeast. Photo shows interim and project areas.



Figure 4: Photo taken from northwest end of location, facing south. Photo shows interim area.



Figure 5: Photo taken from the west end of location. Photo of vegetation on interim area.



12.22.2015 14:09

Figure 6: Photo taken from southwest end of location, facing north. Photo shows interim area.



12.22.2015 14:09

Figure 7: Photo taken from southwest end of location, facing east. Photo shows interim and project areas.



Figure 8: Photo taken from south end of location, facing north. Photo shows interim and project areas.



Figure 9: Photo taken from southeast corner of location, facing north. Photo of Kochia and Russian thistle weed debris on project area.



Figure 10: Photo taken from west end of location. Photo of musk thistle on project area.



Figure 11: Photo taken from west end of location. Photo of musk thistle on project area.



Figure 12: Photo taken from west end of location. Photo of musk thistle on project area.



Figure 13: Photo taken northeast end of location, facing west. Photo shows interim and project areas.



Figure 14: Photo taken from northeast end of location, facing south. Photo shows interim and project areas.



Figure 15: Photo taken from north end of location. Photo of musk thistle.



Figure 16: Photo taken from north end of location. Photo of musk thistle.