

Interim Reclamation Inspection



Photo 1. Photo taken from eastern location, facing West. Location has been minimized for crop production. However, interim reclamation will be reinspected next growing season.

Interim Reclamation Inspection



Photo 2. Photo taken from eastern location, facing South. Location has been minimized for crop production. However, interim reclamation will be reinspected next growing season.

Interim Reclamation Inspection



Photo 3. Photo taken from eastern location, facing North. Location has been minimized for crop production. However, interim reclamation will be reinspected next growing season.