

Interim Reclamation Inspection



Photo 1. Photo taken from southwestern location, facing East. Kochia sp. and Russian thistle dominant vegetative growth inhabiting perennial vegetative establishment. Mechanical means (e.g. mowing) to control undesirable species (Kochia sp. and Russian thistle) is being performed.

Interim Reclamation Inspection



Photo 2. Photo taken from western location, facing North. Kochia sp. and Russian thistle dominant vegetative growth inhabiting perennial vegetative establishment. Mechanical means (e.g. mowing) to control undesirable species (Kochia sp. and Russian thistle) is being performed.

Interim Reclamation Inspection



Photo 3. Photo taken from northern location, facing East. Kochia sp. and Russian thistle dominant vegetative growth inhabiting perennial vegetative establishment. Mechanical means (e.g. mowing) to control undesirable species (Kochia sp. and Russian thistle) is being performed.

Interim Reclamation Inspection



Photo 4. Photo taken from southern location, facing North. Kochia sp. and Russian thistle dominant vegetative growth inhabiting perennial vegetative establishment. This area should be managed (e.g. mow) to reduce undesirable seed sources onto the interim reclamation area.

Interim Reclamation Inspection



Photo 5. Photo taken from general interim reclamation area indicating lack of perennial vegetative growth.