

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date: 12/08/2015
Document Number: 682400212
Overall Inspection: SATISFACTORY

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	<u>432437</u>	<u>432437</u>	<u>Binschus, Chris</u>	<input type="checkbox"/>	

Operator Information:

OGCC Operator Number: 100185
Name of Operator: ENCANA OIL & GAS (USA) INC
Address: 370 17TH ST STE 1700
City: DENVER State: CO Zip: 80202-

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED
- INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
		cogcc.djinspections@encana.com	All inspections

Compliance Summary:

QtrQtr: NWNE Sec: 34 Twp: 2N Range: 68W

Inspector Comment:

This is an interim reclamation inspection.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
432434	WELL	PR	04/10/2014	OW	123-37105	Billings 1D-34H	PR	<input checked="" type="checkbox"/>
432435	WELL	PR	04/10/2014	OW	123-37106	Billings 1A-34H	PR	<input checked="" type="checkbox"/>
432436	WELL	PR	04/10/2014	OW	123-37107	Billings 1B-34H	PR	<input checked="" type="checkbox"/>
432438	WELL	PR	07/08/2014	OW	123-37108	Billings 1F-34H	PR	<input checked="" type="checkbox"/>
432439	WELL	PR	04/10/2014	OW	123-37109	Billings 1E-34H	PR	<input checked="" type="checkbox"/>
432440	WELL	PR	07/08/2014	OW	123-37110	Billings 1C-34H	PR	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>6</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>6</u>	Separators: <u>6</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: <u>9</u>	Oil Tanks: <u>24</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:				
Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Emergency Contact Number (S/AR): _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:				
Type	Area	Volume	Corrective action	CA Date

Multiple Spills and Releases?

Fencing/:				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Equipment:				
Type:	#	Satisfactory/Action Required:		
Comment				
Corrective Action				Date:

Venting:	
Yes/No	
Comment	

Flaring:			
Type	Satisfactory/Action Required		
Comment:			
Corrective Action:			Correct Action Date:

Predrill

Location ID: 432437

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 432434 Type: WELL API Number: 123-37105 Status: PR Insp. Status: PR

Facility ID: 432435 Type: WELL API Number: 123-37106 Status: PR Insp. Status: PR

Facility ID: 432436 Type: WELL API Number: 123-37107 Status: PR Insp. Status: PR

Facility ID: 432438 Type: WELL API Number: 123-37108 Status: PR Insp. Status: PR

Facility ID: 432439 Type: WELL API Number: 123-37109 Status: PR Insp. Status: PR

Facility ID: 432440 Type: WELL API Number: 123-37110 Status: PR Insp. Status: PR

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment: _____
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
Land Use: RANGELAND
Comment: _____
1003a. Waste and Debris removed? Pass
CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? Pass
CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____
CM _____
CA _____ CA Date _____
Guy line anchors marked? _____
CM _____
CA _____ CA Date _____
1003b. Area no longer in use? In Production areas stabilized ? Pass
1003c. Compacted areas have been cross ripped? _____
1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
Cuttings management: _____
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation In

1003 f. Weeds Noxious weeds? _____

Comment: Location lacks perennial vegetative growth. See COGCC comments.

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location

Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____

Corrective Date: _____

Comment: _____

CA: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>Kochia sp. and Russian thistle dominant vegetative growth inhabiting perennial vegetative establishment for most of the interim reclamation area. Mechanical means (e.g. mowing) to control undesirable species (Kochia sp. and Russian thistle) should continue. The southern area hasn't been mowed and this will continue to be a seed source in the future for undesirable plant species like Kochia sp. and Russian thistle. Refer to photos in Doc.#400385538 taken on 10/18/2012 by JR Land Surveying, LLC to reference predisturbance vegetative conditions.</p> <p>Overall Interim Reclamation In Process.</p> <p>Refer to attached photos in Doc.#682400213</p>	binschusc	12/30/2015

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682400213	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3750384