

Abandoned Location Inspection



Photo 1. Photo taken of PR well API 123-31185 which is one of three wells built at location confirming the AL status of API 123-31180.

Abandoned Location Inspection



Photo 2. Photo taken of PR well API 123-31340 which is one of three wells built at location confirming the AL status of API 123-31180.

Abandoned Location Inspection



Photo 3. Photo taken of PR well API 123-17530 which is one of three wells built at location confirming the AL status of API 123-31180.