

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/29/2015

Document Number:

680100394

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	293334	335551	Colby, Lou	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 602 SAWYER STREET #710City: HOUSTON State: TX Zip: 77007

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
Bleil, Rob	970-329-4373	rbleil@ursaresources.com	
Knudson, Dwayne	(970) 456-3335	dknudson@ursaresources.com	
Lind, Jennifer		jlind@ursaresources.com	

Compliance Summary:QtrQtr: SWNW Sec: 17 Twp: 6S Range: 92W**Inspector Comment:**

This is an Abandoned Location Inspection for Seven Wells; API#s 045-14949, 14948, 14944, 14943, 18204, 18205, 18206. It does not appear that these Wells were drilled on Location with producing Wells 045-14947, 14946, 14945, 14942, 14941; Therefore, these are Well releases on an Active Location.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
293334	WELL	AL	07/17/2014	LO	045-14949	Dever C11	RI	<input checked="" type="checkbox"/>
293335	WELL	AL	09/12/2014	LO	045-14948	Dever C10	RI	<input checked="" type="checkbox"/>
293336	WELL	PR	09/01/2015	GW	045-14947	DEVER C9	PR	<input type="checkbox"/>
293337	WELL	PR	11/06/2007	GW	045-14946	DEVER C8	PR	<input type="checkbox"/>
293338	WELL	PR	12/24/2013	GW	045-14945	Dever C7	PR	<input type="checkbox"/>
293339	WELL	AL	07/17/2014	LO	045-14944	Dever C6	RI	<input checked="" type="checkbox"/>
293340	WELL	AL	07/17/2014	LO	045-14943	Dever C5	RI	<input checked="" type="checkbox"/>
293341	WELL	PR	07/08/2010	GW	045-14942	DEVER C4	PR	<input type="checkbox"/>
293342	WELL	PR	07/11/2013	GW	045-14941	DEVER C3	PR	<input type="checkbox"/>
293343	WELL	AL	07/17/2014	LO	045-14940	Dever C2	AL	<input type="checkbox"/>

Inspector Name: Colby, Lou

293344	WELL	AL	11/13/2014	LO	045-14939	Dever C1	AL	<input type="checkbox"/>
301600	WELL	AL	08/22/2012	LO	045-18204	DEVER C14	RI	<input checked="" type="checkbox"/>
301601	WELL	AL	08/15/2012	LO	045-18205	DEVER C13	RI	<input checked="" type="checkbox"/>
301602	WELL	AL	08/30/2012	LO	045-18206	DEVER C12	RI	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Emergency Contact Number (S/AR): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Equipment:

Type:	#	Satisfactory/Action Required:
Comment		
Corrective Action		Date: _____

Venting:

Inspector Name: Colby, Lou

Yes/No	
Comment	

Flaring:

Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 293334

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

--

Summary of Operator Response to Landowner Issues:

--

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

--

Facility

Facility ID: 293334 Type: WELL API Number: 045-14949 Status: AL Insp. Status: RI

Facility ID: 293335 Type: WELL API Number: 045-14948 Status: AL Insp. Status: RI

Inspector Name: Colby, Lou

Facility ID:	293339	Type:	WELL	API Number:	045-14944	Status:	AL	Insp. Status:	RI
Facility ID:	293340	Type:	WELL	API Number:	045-14943	Status:	AL	Insp. Status:	RI
Facility ID:	301600	Type:	WELL	API Number:	045-18204	Status:	AL	Insp. Status:	RI
Facility ID:	301601	Type:	WELL	API Number:	045-18205	Status:	AL	Insp. Status:	RI
Facility ID:	301602	Type:	WELL	API Number:	045-18206	Status:	AL	Insp. Status:	RI

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____

CM _____

CA _____ CA Date _____

Inspector Name: Colby, Lou

Guy line anchors marked? _____

CM _____

CA _____

CA Date _____

1003b. Area no longer in use? _____

Production areas stabilized? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____

Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: **Crop Ground**

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: **No evidence of these Seven AL Wells on this Active Location.**

Corrective Action: _____

Date _____

Overall Final Reclamation Pass

Well Release on Active Location ☒

Multi-Well Location ☒

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Inspector Name: Colby, Lou

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680100404	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3751675