

Inspector Name: Peterson, Tom

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/05/2016

Document Number:

680701197

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	296890	310776	Peterson, Tom	<input type="checkbox"/>	

**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

**Contact Information:**

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	All inspections

**Compliance Summary:**QtrQtr: SESW Sec: 21 Twp: 4N Range: 66W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/20/2012	661601156	PR	PR	SATISFACTORY			No
06/06/2011	200312101	PR	PR	SATISFACTORY	I		No

**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
296890	WELL	PR	02/06/2009	GW	123-26957	KISSLER K 21-25	PR	<input checked="" type="checkbox"/>

**Equipment:**Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location****Lease Road:**

Type	Satisfactory/Action Required	comment	Corrective Action	Date

<b>Signs/Marker:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	SATISFACTORY			
WELLHEAD	SATISFACTORY			
BATTERY	SATISFACTORY			

Emergency Contact Number (S/AR): SATISFACTORY

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

<b>Good Housekeeping:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

<b>Spills:</b>				
Type	Area	Volume	Corrective action	CA Date

☐ Multiple Spills and Releases?

<b>Fencing/:</b>				
Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date
Panel	SATISFACTORY	Wellhead		
Livestock	SATISFACTORY	Separator		

<b>Equipment:</b>					
Type: Gas Meter Run	# 2		Satisfactory/Action Required:	SATISFACTORY	
Comment					
Corrective Action					Date:
Type: Ancillary equipment	# 4		Satisfactory/Action Required:	SATISFACTORY	
Comment	Two automation arrays and two ECD scrubbers				
Corrective Action					Date:
Type: Emission Control Device	# 2		Satisfactory/Action Required:	SATISFACTORY	
Comment					
Corrective Action					Date:
Type: Bird Protectors	# 4		Satisfactory/Action Required:	SATISFACTORY	
Comment					
Corrective Action					Date:
Type: Horizontal Heated Separator	# 2		Satisfactory/Action Required:	SATISFACTORY	
Comment					
Corrective Action					Date:
Type: Plunger Lift	# 1		Satisfactory/Action Required:	SATISFACTORY	
Comment					

Inspector Name: Peterson, Tom

Corrective Action	Date:
-------------------	-------

**Facilities:** ☐ New Tank Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST	,

S/AR	SATISFACTORY	Comment:
------	--------------	----------

Corrective Action:	Corrective Date:
--------------------	------------------

Paint

Condition	Adequate
-----------	----------

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action	Corrective Date
-------------------	-----------------

Comment
---------

**Facilities:** ☐ New Tank Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	2	<100 BBLS	BV CONCRETE	,

S/AR	SATISFACTORY	Comment: 60 bbls
------	--------------	------------------

Corrective Action:	Corrective Date:
--------------------	------------------

Paint

Condition	Adequate
-----------	----------

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action	Corrective Date
-------------------	-----------------

Comment
---------

Venting:

Yes/No	NO
--------	----

Comment
---------

Flaring:

Type	Satisfactory/Action Required
------	------------------------------

Comment: \_\_\_\_\_

Corrective Action:	Correct Action Date:
--------------------	----------------------

**Predrill**

Location ID: 296890

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

S/AR: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

S/AR: \_\_\_\_\_ Comment: \_\_\_\_\_

CA: \_\_\_\_\_ Date: \_\_\_\_\_

**Wildlife BMPs:**

S/AR: \_\_\_\_\_ Comment: \_\_\_\_\_

CA: \_\_\_\_\_ Date: \_\_\_\_\_

Comment: \_\_\_\_\_

**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 296890 Type: WELL API Number: 123-26957 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

**BradenHead**

Comment: Bradenhead is exposed at surface.

CA: \_\_\_\_\_

CA Date: \_\_\_\_\_

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Inspector Name: Peterson, Tom

Comment: <input style="width:700px" type="text"/>		
Corrective Action: _____		Date: _____
Reportable: _____	GPS: Lat _____	Long _____
Proximity to Surface Water: _____	Depth to Ground Water: _____	
<b>Water Well:</b>		
		Lat _____ Long _____
DWR Receipt Num: _____	Owner Name: _____	GPS : _____
<b>Field Parameters:</b>		
<input style="width:300px" type="text"/>		
Sample Location: <input style="width:400px" type="text"/>		
Emission Control Burner (ECB): Y _____		
Comment: _____		
Pilot: ON _____	Wildlife Protection Devices (fired vessels): YES _____	

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: _____	Date Interim Reclamation Completed: _____
Land Use: _____	
Comment: <input style="width:750px" type="text"/>	
1003a. Waste and Debris removed? <u>Pass</u>	
CM _____	
CA _____	CA Date _____
Unused or unneeded equipment onsite? <u>Pass</u>	
CM _____	
CA _____	CA Date _____
Pit, cellars, rat holes and other bores closed? <u>Pass</u>	
CM _____	
CA _____	CA Date _____
Guy line anchors marked? _____	
CM _____	
CA _____	CA Date _____
1003b. Area no longer in use? _____	Production areas stabilized ? _____
1003c. Compacted areas have been cross ripped? _____	
1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____	
Cuttings management: _____	
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____	
Production areas have been stabilized? _____	Segregated soils have been replaced? _____
<b>RESTORATION AND REVEGETATION</b>	
<u>Cropland</u>	
Top soil replaced _____	Recontoured _____ Perennial forage re-established _____

Inspector Name: Peterson, Tom

**Non-Cropland**

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_

Well Release on Active Location ☐

Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

S/A/V: SATISFACTOR Y \_\_\_\_\_

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

Pits: ☐ NO SURFACE INDICATION OF PIT