

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/02/2016

Document Number:

680100416

Overall Inspection:

SATISFACTORY**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	295456	336037	Colby, Lou	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 10079Name of Operator: ANTERO RESOURCES PICEANCE LLCAddress: 1625 17TH ST STE 300City: DENVER State: CO Zip: 80202

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

Contact Name	Phone	Email	Comment
		astelee@anteroresources.com	FR/Bond Release Insp.

Compliance Summary:QtrQtr: NWNE Sec: 14 Twp: 6S Range: 93W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
06/11/2013	670200553	XX	UN	SATISFACTORY			No
12/10/2010	200287168	PR	ND	SATISFACTORY			No
08/15/2007	200193844	DG	DG	SATISFACTORY			No

Inspector Comment:

This is an Abandoned Location inspection for Wells API#s 045-15762, 15763 16014, 16037, 16040, 17626. It does not appear that these AL Wells were drilled on Location with four producing and one DG wells; therefore, these are Well releases on an Active Location. COGCC Records indicate Permits were Abandoned 6/24/13.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
295456	WELL	AL	06/24/2013	LO	045-15762	Gypsum Ranch B1	RI	<input checked="" type="checkbox"/>
295457	WELL	AL	06/24/2013	LO	045-15763	Gypsum Ranch B2	RI	<input checked="" type="checkbox"/>
296416	WELL	PR	06/10/2008	GW	045-16013	GYPSUM RANCH B3	PR	<input type="checkbox"/>
296417	WELL	AL	06/24/2013	LO	045-16014	Gypsum Ranch B12	RI	<input checked="" type="checkbox"/>
296454	WELL	PR	06/13/2008	GW	045-16036	GYPSUM RANCH B4	PR	<input type="checkbox"/>
296455	WELL	AL	06/24/2013	LO	045-16037	Gypsum Ranch B5	AL	<input type="checkbox"/>
296456	WELL	AL	06/24/2013	LO	045-16038	Gypsum Ranch B6	RI	<input checked="" type="checkbox"/>
296457	WELL	DG	04/16/2008	GW	045-16039	GYPSUM RANCH B7	DG	<input type="checkbox"/>

Inspector Name: Colby, Lou

296458	WELL	AL	06/24/2013	LO	045-16040	Gypsum Ranch B8	RI	<input checked="" type="checkbox"/>
296459	WELL	PR	06/13/2008	GW	045-16041	GYPSUM RANCH B9	PR	<input type="checkbox"/>
296460	WELL	AL	06/24/2013	LO	045-16042	Gypsum Ranch B11	AL	<input type="checkbox"/>
296461	WELL	PR	02/01/2012	GW	045-16043	GYPSUM RANCH B13	PR	<input type="checkbox"/>
299255	WELL	AL	06/24/2013	LO	045-17626	Gypsum Ranch B10	RI	<input checked="" type="checkbox"/>
426957	NONFACILIT Y	AC	12/19/2011		-	GYPSUM RANCH B PAD	AC	<input type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Emergency Contact Number (S/AR): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date

☐ Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Equipment:

Type:	#	Satisfactory/Action Required:

Inspector Name: Colby, Lou

Comment	
Corrective Action	Date:

Venting:

Yes/No	
Comment	

Flaring:

Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 295456

Site Preparation:

Lease Road Adeq.: Pads: Soil Stockpile:

S/AR:

Corrective Action: Date: CDP Num.:

Form 2A COAs:

S/AR: **Comment:**

CA: **Date:**

Wildlife BMPs:

S/AR: **Comment:**

CA: **Date:**

Comment:

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: Address: Phone Number: Cell Phone:

Operator Rep. Contact Information:

Landman Name: Phone Number: Date Onsite Request Received: Date of Rule 306 Consultation:

Request LGD Attendance:

LGD Contact Information:

Name: Phone Number: Agreed to Attend:

Summary of Landowner Issues:

--

Summary of Operator Response to Landowner Issues:

--

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

--

Facility

Inspector Name: Colby, Lou

Facility ID:	295456	Type:	WELL	API Number:	045-15762	Status:	AL	Insp. Status:	RI
Facility ID:	295457	Type:	WELL	API Number:	045-15763	Status:	AL	Insp. Status:	RI
Facility ID:	296417	Type:	WELL	API Number:	045-16014	Status:	AL	Insp. Status:	RI
Facility ID:	296456	Type:	WELL	API Number:	045-16038	Status:	AL	Insp. Status:	RI
Facility ID:	296458	Type:	WELL	API Number:	045-16040	Status:	AL	Insp. Status:	RI
Facility ID:	299255	Type:	WELL	API Number:	045-17626	Status:	AL	Insp. Status:	RI

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Waste and Debris removed? _____

CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____

CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____

Inspector Name: Colby, Lou

CM _____

CA _____

CA Date _____

Guy line anchors marked? _____

CM _____

CA _____

CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: **Industrial/ Gravel Pit**

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: **No evidence of these Six AL Wells on this Active Location.**

Corrective Action: _____

Date _____

Overall Final Reclamation Pass

Well Release on Active Location ☒

Multi-Well Location ☒

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Inspector Name: Colby, Lou

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680100418	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3755993