

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/02/2016

Document Number:

680100419

Overall Inspection:

ACTION REQUIRED**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	2A Doc Num:
	296454	336037	Colby, Lou	<input type="checkbox"/>	

Operator Information:OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 602 SAWYER STREET #710City: HOUSTON State: TX Zip: 77007☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED☒ INSPECTOR REQUESTS FORM 42 WHEN
CORRECTIVE ACTIONS ARE COMPLETED**Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	(970) 456-3335	dknudson@ursaresources.com	
Bleil, Rob	970-329-4373	rbleil@ursaresources.com	
Lind, Jennifer		jlind@ursaresources.com	

Compliance Summary:

QtrQtr:	NWNE	Sec:	14	Twp:	6S	Range:	93W
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Action Required	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
12/10/2010	200287171	PR	PR	SATISFACTORY			No
06/25/2010	200261397	SR	PR	SATISFACTORY			No
08/15/2007	200193837	DG	DG	SATISFACTORY			No

Inspector Comment:

This is an Abandoned Location Inspection for Wells API 045-16037 and 045-16042. It does not appear that these two wells were drilled on Location with one DG and four Producing Wells. Sundry notices for abandoning APDs were submitted 6/24/2013. The two AL Wells do have Conductors Set; triggering this to be an Action Required Inspection.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	
295456	WELL	AL	06/24/2013	LO	045-15762	Gypsum Ranch B1	AL	<input type="checkbox"/>
295457	WELL	AL	06/24/2013	LO	045-15763	Gypsum Ranch B2	AL	<input type="checkbox"/>
296416	WELL	PR	06/10/2008	GW	045-16013	GYPSUM RANCH B3	PR	<input type="checkbox"/>
296417	WELL	AL	06/24/2013	LO	045-16014	Gypsum Ranch B12	AL	<input type="checkbox"/>
296454	WELL	PR	06/13/2008	GW	045-16036	GYPSUM RANCH B4	PR	<input type="checkbox"/>
296455	WELL	AL	06/24/2013	LO	045-16037	Gypsum Ranch B5	RI	<input checked="" type="checkbox"/>
296456	WELL	AL	06/24/2013	LO	045-16038	Gypsum Ranch B6	AL	<input type="checkbox"/>

Inspector Name: Colby, Lou

296457	WELL	DG	04/16/2008	GW	045-16039	GYPSUM RANCH B7	DG	<input type="checkbox"/>
296458	WELL	AL	06/24/2013	LO	045-16040	Gypsum Ranch B8	AL	<input type="checkbox"/>
296459	WELL	PR	06/13/2008	GW	045-16041	GYPSUM RANCH B9	PR	<input type="checkbox"/>
296460	WELL	AL	06/24/2013	LO	045-16042	Gypsum Ranch B11	RI	<input checked="" type="checkbox"/>
296461	WELL	PR	02/01/2012	GW	045-16043	GYPSUM RANCH B13	PR	<input type="checkbox"/>
299255	WELL	AL	06/24/2013	LO	045-17626	Gypsum Ranch B10	AL	<input type="checkbox"/>
426957	NONFACILIT Y	AC	12/19/2011		-	GYPSUM RANCH B PAD	AC	<input type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Action Required	comment	Corrective Action	Date

Signs/Marker:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Emergency Contact Number (S/AR): _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Action Required	Comment	Corrective Action	CA Date

Inspector Name: Colby, Lou

Equipment:			
Type:	#	Satisfactory/Action Required:	
Comment			
Corrective Action			Date:

Venting:	
Yes/No	
Comment	

Flaring:			
Type		Satisfactory/Action Required	
Comment:			
Corrective Action:		Correct Action Date:	

Predrill

Location ID: 296454

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

S/AR: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

S/AR: _____ **Comment:** _____

CA: _____ **Date:** _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

--

Summary of Operator Response to Landowner Issues:

--

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

--

Facility

Facility ID: 296455 Type: WELL API Number: 045-16037 Status: AL Insp. Status: RI

Facility ID: 296460 Type: WELL API Number: 045-16042 Status: AL Insp. Status: RI

Environmental**Spills/Releases:**

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

Water Well:

DWR Receipt Num: Owner Name: GPS : Lat Long

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Waste and Debris removed?

CM

CA CA Date

Unused or unneeded equipment onsite?

CM

CA CA Date

Pit, cellars, rat holes and other bores closed?

CM

CA CA Date

Guy line anchors marked?

CM

CA CA Date

1003b. Area no longer in use?

Production areas stabilized ?

Inspector Name: Colby, Lou

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: Wells with Abandoned Permits have conductors set

Corrective Action: Plug /Close Conductors on two AL Wells with Conductors set. Date 03/11/2016

Overall Final Reclamation **Fail** Well Release on Active Location ☐ Multi-Well Location ☒

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/A/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Inspector Name: Colby, Lou

Document Num	Description	URL
680100420	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3756296