



A photograph showing a vertical pipe with a valve assembly inside a shed. The pipe is white and runs vertically. The valve assembly is located near the bottom of the frame. The shed has a corrugated metal ceiling and a concrete floor. Sunlight is streaming in from the right, casting a strong shadow of the pipe and valve onto the floor. The text "Picture of inside meter shed at Hunt #1. No meter equipment" is overlaid on the right side of the image.

Picture of inside
meter shed at Hunt #1.
No meter equipment

MIAMBARK OIL & GAS CO.

HUNT # 1

Loc. NW-SE

Sec. 30-31-41

Baca Co. Colo.

Old lease sign and
no lease sign showing
current operator



Current well status
is Shut In