

Abandoned Location Inspection



Photo 1. Photo taken at location. It appears this location was never built. However, need to remove fence post before passing final reclamation.